

Anlage 17.18.7

Fotodokumentation




Bild 1. EÜ Gutleutstraße, S/B/DPH 126



Bild 2. EÜ Gutleutstraße; S/B/DPH 127



Bild 3. EÜ Gutleutstraße; S/B/DPH 127



Bild 4. S/RKS/DPL-5 125




Bild 5. S/RKS/DPL-5 128



Bild 6. Bohrung S/B 126: 0,0 - 4,0 m



Bild 7. Bohrung S/B 126: 4,0 - 8,0 m



Bild 8. Bohrung S/B 126: 8,0 - 12,0 m



Bild 9. Bohrung S/B 126: 12,0 - 16,0 m



Bild 10. Bohrung S/B 126: 16,0 - 20,0 m



Bild 11. Bohrung S/B 127: 0,0 - 4,0 m



Bild 12. Bohrung S/B 127: 4,0 - 8,0 m



Bild 13. Bohrung S/B 127: 8,0 - 12,0 m



Bild 14. Bohrung S/B 127: 12,0 - 16,0 m



Bild 15. Bohrung S/B 127: 16,0 - 20,0 m

